Massachusetts Cultural Resource Information System

Scanned Record Cover Page

Inventory No: SBR.145

Historic Name: Fay, S. House

Common Name: O'Brien - Tufts, Charles House

Address: 3 Wood St

City/Town: Southborough

Village/Neighborhood: Southville

Local No: 2-40

Year Constructed: c 1870

Architect(s):

Architectural Style(s): Greek Revival

Use(s): Single Family Dwelling House

Significance: Architecture


Area(s): SBR.B: Southville

Designation(s):

Roof: Asphalt Shingle

Building Materials(s): Wall: Wood Shingle; Wood

Foundation: Stone, Uncut



The Massachusetts Historical Commission (MHC) has converted this paper record to digital format as part of ongoing projects to scan records of the Inventory of Historic Assets of the Commonwealth and National Register of Historic Places nominations for Massachusetts. Efforts are ongoing and not all inventory or National Register records related to this resource may be available in digital format at this time.

The MACRIS database and scanned files are highly dynamic; new information is added daily and both database records and related scanned files may be updated as new information is incorporated into MHC files. Users should note that there may be a considerable lag time between the receipt of new or updated records by MHC and the appearance of related information in MACRIS. Users should also note that not all source materials for the MACRIS database are made available as scanned images. Users may consult the records, files and maps available in MHC's public research area at its offices at the State Archives Building, 220 Morrissey Boulevard, Boston, open M-F, 9-5.

Users of this digital material acknowledge that they have read and understood the MACRIS Information and Disclaimer (http://mhc-macris.net/macrisdisclaimer.htm)

Data available via the MACRIS web interface, and associated scanned files are for information purposes only. THE ACT OF CHECKING THIS DATABASE AND ASSOCIATED SCANNED FILES DOES NOT SUBSTITUTE FOR COMPLIANCE WITH APPLICABLE LOCAL, STATE OR FEDERAL LAWS AND REGULATIONS. IF YOU ARE REPRESENTING A DEVELOPER AND/OR A PROPOSED PROJECT THAT WILL REQUIRE A PERMIT, LICENSE OR FUNDING FROM ANY STATE OR FEDERAL AGENCY YOU MUST SUBMIT A PROJECT NOTIFICATION FORM TO MHC FOR MHC'S REVIEW AND COMMENT. You can obtain a copy of a PNF through the MHC web site (www.sec.state.ma.us/mhc) under the subject heading "MHC Forms."

Commonwealth of Massachusetts
Massachusetts Historical Commission
220 Morrissey Boulevard, Boston, Massachusetts 02125
www.sec.state.ma.us/mhc

This file was accessed on:

B South borough ddress 3 Wood Street liginal & present dwelling lowner Fred Sanchieu public Style Liveraure immens Music Other Architect Architect Architect Archi		145 145
idress 3 Nood Street iginal & present dwelling towner Fred Sanchetic public Style Style Other Development of town/city Architectural reason for inventorying: OR part of Area # 3. CONDITION Excellent Good Fair Deteriorated Moved Altered Added 4. DESCRIPTION FOUNDATION/BASEMENT: High Regular Low Material WALL COVER: Wood Street WALL COVER: Wood Street WALL COVER: Wood Street WALL COVER: Wood Street FORCHES: 1 2 3 4 Center End Interior Irregular Cluster Elaborate STORIES: 1 2 3 4 ATTACHMENTS: Wings Ell Shed PORCHES: 1 2 3 4 Frest State PORCHES: 3 4 ATTACHMENTS: Wings Ell Shed PORCHES: Gable end: Front/side Ornament Entrance: Side Front: Center Side Details: Windows: Spacing: Regular Irregular Identical/Varied Corners: Tain Hasters Quoins Cornerboards Corners: Tain Hasters Quoins Cornerboards Recorder For Photo # 47 Pate 1971 Photo # 47 Pate 1971		CRUZ MAR
idress 3 Nood Street iginal & present dwelling towner Fred Sanchesis public Development of town/city Architectural reason for inventorying: Architectural reason for inventorying: OR part of Area # 3. CONDITION Excellent Good Fair Deteriorated Moved Altered Added 4. DESCRIPTION FOUNDATION/BASEMENT: High Regular Low Material WALL COVER: Wood Street WALL COVER: Wood Street WALL COVER: Wood Street FOOF: Widge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork CHIMNEYS: 2 3 4 Center End Interior Irregular Cluster Elaborate STORIES: 1 2 3 4 ATTACHMENTS: Wing Ell Shed PORCHES: 1 2 3 4 Frest State PORTICO Balcony FACADE: Gable end: Front; Center Side Details: Windows: Spacing: Regular Irregular Identical/Varied Corners: Tain Hasters Quoins Cornerboards Attack Corners: Tain Hasters Quoins Cornerboards Attack Property has feet frontage on street Recorder For Apple 1974 Pate 1971		
Literature Indians Source of date Music Other Development of town/city Architectural reason for inventorying: Architectural		Southborough
Literature Indians Source of date Architect Architect Architect Architectural reason for inventorying: Architectural reason for inventorying: Architectural reason for inventorying: Architectural reason for inventorying: Architect Architect Architect Architect Archite		ddress 3 Wood Street
LITERATURE MOIANS Source of date Music Development of town/city Architectural reason for inventorying: Architectural reason for inventorying: OR part of Area # 3. CONDITION Excellent Good Fair Deteriorated Moved Altered Added 4. DESCRIPTION FOUNDATION/BASEMENT: High Regula Low Material WALL COVER: Wood Wolf Brick Stone Other ROOF: Ridge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork CHIMNEYS() 2 3 4 Center End Interior Irregular Cluster Elaborate STORIES: 1 2 3 4 ATTACHMENTS: Wings Ell Shed PORCHES: 1) 2 3 4 Free Stall PORTICO Balcony FACADE: Gable end: Front: Center Side Details: Windows: Spacing: Riegular Irregular Identical/Varied Corners: Riain Hlasters Quoins Cornerboards 5. Indicate location of building in relation to nearest cross streets and other buildings 6. Footage of structure from street Property has feet frontage on street Recorder For Photo # 47		
LITERATURE MOIANS Source of date Music Development of town/city Architectural reason for inventorying: Architectural reason for inventorying: OR part of Area # 3. CONDITION Excellent Good Fair Deteriorated Moved Altered Added 4. DESCRIPTION FOUNDATION/BASEMENT: High Regula Low Material WALL COVER: Wood Wolf Brick Stone Other ROOF: Ridge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork CHIMNEYS() 2 3 4 Center End Interior Irregular Cluster Elaborate STORIES: 1 2 3 4 ATTACHMENTS: Wings Ell Shed PORCHES: 1) 2 3 4 Free Stall PORTICO Balcony FACADE: Gable end: Front: Center Side Details: Windows: Spacing: Riegular Irregular Identical/Varied Corners: Riain Hlasters Quoins Cornerboards 5. Indicate location of building in relation to nearest cross streets and other buildings 6. Footage of structure from street Property has feet frontage on street Recorder For Photo # 47		signal & progent duralling
Development of town/city Architectural reason for inventorying: OR part of Area # 3. CONDITION Excellent Good Fair Deteriorated Moved Altered Added 4. DESCRIPTION FOUNDATION/BASEMENT: High Regula Low Material Structure ROOF: Ridge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork CHIMNEYS: 1 2 3 4 Center End Interior Irregular Cluster Elaborate STORIES: 1 2) 3 4 ATTACHMENTS: Rings Ell Shed PORCHES: 0 2 3 4 Front Stude Dorment Entrance: Side Front; Center Side Details: Windows: Spacing: Regular/Irregular Identical/Varied Corners: Main Filasters Quoins Cornerboards Architect A		
Nusic Other Development of town/city Architectural reason for inventorying: OR part of Area # 3. CONDITION Excellent Good Fair Deteriorated Moved Altered Added 4. DESCRIPTION FOUNDATION/BASEMENT: High Regulal Low Material WALL COVER: Wood Arabe Brick Stone Other ROOF: Ridge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork CHIMNEYS: 1 2 3 4 Center End Interior Irregular Cluster Elaborate STORIES: 1 3 4 ATTACHMENTS: Wings Ell Shed PORCHES: 1 2 3 4 Front Side Ornament Entrance: Side Front: Center Side Details: Windows: Spacing: Regular Irregular Identical/Varied Corners: Plain pilasters Quoins Cornerboards 5. Indicate location of building in relation to nearest cross streets and other buildings Recorder For Photo # 47 Date (M)		
Nusic Other Development of town/city Architectural reason for inventorying: OR part of Area # 3. CONDITION Excellent Good Fair Deteriorated Moved Altered Added 4. DESCRIPTION FOUNDATION/BASEMENT: High Regulal Low Material WALL COVER: Wood Arabe Brick Stone Other ROOF: Ridge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork CHIMNEYS: 1 2 3 4 Center End Interior Irregular Cluster Elaborate STORIES: 1 3 4 ATTACHMENTS: Wings Ell Shed PORCHES: 1 2 3 4 Front Side Ornament Entrance: Side Front: Center Side Details: Windows: Spacing: Regular Irregular Identical/Varied Corners: Plain pilasters Quoins Cornerboards 5. Indicate location of building in relation to nearest cross streets and other buildings Recorder For Photo # 47 Date (M)		public
Music Other Development of town/city Architectural reason for inventorying: OR part of Area # 3. CONDITION Excellent Good Fair Deteriorated Moved Altered Added 4. DESCRIPTION FOUNDATION/BASEMENT: High Regulan Low Material WALL COVER: Wood Air Brick Stone Other ROOF: Ridge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork CHIMNEYS(1) 2 3 4 Center End Interior Irregular Cluster Elaborate STORIES: 1 2) 3 4 ATTACHMENTS: Wings Ell Shed PORCHES: 1) 2 3 4 Front Stall PORTICO Balcony FACADE: Gable end: Front/side Ornament Entrance: Side Front: Center Side Details: Windows: Spacing Regular/Irregular Identical/Varied Corners: Plain Filasters Quoins Cornerboards 5. Indicate location of building in relation to nearest cross streets and other buildings 6. Footage of structure from street Property has feet frontage on street Recorder For Photo # 171 Date 1971		Style
Development of town/city Architectural reason for inventorying: OR part of Area # 3. CONDITION Excellent Good Fair Deteriorated Moved Altered Added 4. DESCRIPTION FOUNDATION/BASEMENT: High Regular Low Material WALL COVER: Wood hinger Brick Stone Other ROOF: Midge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork CHIMNEYS 1 2 3 4 Center End Interior Irregular Cluster Elaborate STORIES: 1 2 3 4 ATTACHMENTS: Wings Ell Shed PORCHES: 1 2 3 4 Front Side Details: PORTICO Balcony FACADE: Gable end: Front side Ornament Entrance: Side Front: Center Side Details: Windows: Spacing: Regular/Irregular Identical/Varied Corners: Plain filasters Quoins Cornerboards 6. Footage of structure from street Property has feet frontage on street Recorder Photo # Photo # Port 1971 Page 1971		rce of date
OR part of Area # 3. CONDITION Excellent Good Fair Deteriorated Moved Altered Added 4. DESCRIPTION FOUNDATION/BASEMENT: High Regular Low Material WALL COVER: Wood Arrack Brick Stone Other ROOF: Ridge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork CHIMNEYS: 1 2 3 4 Center End Interior Irregular Cluster Elaborate STORIES: 1 2 3 4 ATTACHMENTS: Wings Ell Shed PORCHES: 1 2 3 4 Front Side PORTICO Balcony FACADE: Gable end: Front/side Ornament Entrance: Side Front: Center Side Details; Windows: Spacing: Regular Irregular Identical/Varied Corners: Plain Pilasters Quoins Cornerboards 6. Footage of structure from street Property has feet frontage on street Recorder For Photo # Port Date (A7)	Development of town/city Arch	nitect
3. CONDITION Excellent Good Fair Deteriorated Moved Altered Added 4. DESCRIPTION FOUNDATION/BASEMENT: High Regular Low Material Stone WALL COVER: Wood Airack Brick Stone Other ROOF: Ridge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork CHIMNEYS: 1 2 3 4 Center End Interior Irregular Cluster Elaborate STORIES: 1 2 3 4 ATTACHMENTS: Wings Ell Shed PORCHES: 1 2 3 4 Front Side PORTICO Balcony FACADE: Gable end: Front; Center Side Details: Windows: Spacing: Regular Irregular Identical/Varied Corners: Flain Filasters Quoins Cornerboards Cultured 5. Indicate location of building in relation to nearest cross streets and other buildings 6. Footage of structure from street Property has feet frontage on street Recorder For Photo # Pate (AT)	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
4. DESCRIPTION FOUNDATION/BASEMENT: High Regular Low Material Stone WALL COVER: Wood Shirdle Brick Stone Other ROOF: Ridge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork CHIMNEYS: 1 2 3 4 Center End Interior Irregular Cluster Elaborate STORIES: 1 2 3 4 ATTACHMENTS: Wings Ell Shed PORTICO Balcony FACADE: Gable end: Front side Ornament Entrance: Side Front: Center Side Details: Windows: Spacing: Regular Irregular Identical/Varied Corners: Tain illasters Quoins Cornerboards Attack 5. Indicate location of building in relation to nearest cross streets and other buildings Property has feet frontage on street Recorder Recorder Photo # 4 4 4 Date 1971	BRLIOGRAPH AND/OR REFERENCE	
WALL COVER: Wood Achael Brick Stone Other ROOF: Ridge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork CHIMNEYS: 1 2 3 4 Center End Interior Irregular Cluster Elaborate STORIES: 1 2 3 4 ATTACHMENTS: Wings Ell Shed PORCHES: 1 2 3 4 Front Side Details: PORTICO Balcony FACADE: Gable end: Front side Ornament Entrance: Side Front: Center Side Details: Windows: Spacing: Regular Irregular Identical/Varied Corners: Plain Filasters Quoins Cornerboards 5. Indicate location of building in relation to nearest cross streets and other buildings Recorder Recorder Photo # 4 7 4 Date 1971	3. CONDITION Excellent Good Fair Deteriorated Move	ed Altered Added
WALL COVER: Wood Achael Brick Stone Other ROOF: Ridge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork CHIMNEYS: 1 2 3 4 Center End Interior Irregular Cluster Elaborate STORIES: 1 2 3 4 ATTACHMENTS: Wings Ell Shed PORCHES: 1 2 3 4 Front Side Details: PORTICO Balcony FACADE: Gable end: Front side Ornament Entrance: Side Front: Center Side Details: Windows: Spacing: Regular Irregular Identical/Varied Corners: Plain Filasters Quoins Cornerboards 5. Indicate location of building in relation to nearest cross streets and other buildings Recorder Recorder Photo # 47 Photo Date 1971	4. DESCRIPTION	
WALL COVER: Wood		
ROOF: Ridge Gambrel Flat Hip Mansard Tower Cupola Dormer windows Balustrade Grillwork CHIMNEYS: 1 2 3 4	FOUNDATION, BASEMENT: High Regular Low Material	
Tower Cupola Dormer windows Balustrade Grillwork CHIMNEYS: 1 2 3 4		
STORIES: 1 2 3 4 ATTACHMENTS: Wings Ell Shed		
PORCHES: 1 2 3 4 Front Side Portico Balcony FACADE: Gable end: Front side Ornament Portico Center Side Details: Windows: Spacing: Regular Irregular Identical/Varied Corners: Plain Filasters Quoins Cornerboards Cornerboards 5. Indicate location of building in relation to nearest cross streets and other buildings 6. Footage of structure from street Property has feet frontage on street Recorder For Photo # 4 7 4 Date 491		
Entrance: Side Front: Center Side Details: Windows: Spacing: Regular Irregular Identical/Varied Corners: Plain Pilasters Quoins Cornerboards 5. Indicate location of building in relation to nearest cross streets and other buildings 6. Footage of structure from street Property has feet frontage on street Recorder Photo # 4		
Entrance: Side Front: Center Side Details:	PORCHES: 1 2 3 4 front & Side PORTICO Balcony	
Windows: Spacing: Regular Irregular Identical/Varied	FACADE: Gable end: Front side Ornament	
Corners: Plain Pilasters Quoins Cornerboards 5. Indicate location of building in relation to nearest cross streets and other buildings 6. Footage of structure from street	Entrance: Side Front: Center Side Details:	OR OR SILE (Refer and elaborate on
5. Indicate location of building in relation to nearest cross streets and other buildings 6. Footage of structure from street	Windows: Spacing: Regular Irregular Identical/Varied	
5. Indicate location of building in relation to nearest cross streets and other buildings 6. Footage of structure from street		
nearest cross streets and other buildings Property hasfeet frontage on street Recorder Photo # 474 Date 491		ge of structure from street
For Condens to the Photo # 4-74 Date (97)	nearest cross streets and other buildings Prope	erty hasfeet frontage on street
Photo # 4-74 Date 1971		r
Photo # 4-74 Date (97)		rden: Formal/Informal
11,000 D 51	Photo #	4-74 Date 1971
SEE REVERSE SIL	SEE RE	VERSE SIL

Registry of Deeds

RELATION OF SURROUNDIN() STRUCTURE
1. Outbuildings
2. Landscape Features: Agriculture Open Wooded Garden: Formal/Informal Predominant features Landscape architect
3. Neighboring Structures Style: Colonial Federal Greek Revival Gothic Revival Italian Villa Lombard Rom. Venetian Gothic Mansard Richardsonian Modern
Use: Residential Commercial Religious Conditions: Excellent Good Fair Deteriorated
GIVE A BRIEF DESCRIPTION OF HISTORIC IMPORTANCE OF SITE (Refer and elaborate on theme circled on front of form)
ORCHES: D 2 8 4 Trauz PANA PORTION Balcony
MORIES: 129 4 ATTACHMENTS: Wings Ell Shed
CHIMNEYS (1) 2 3 4 - Center) End Interior Progular Chaster Ellaborate
MALL COVER: Wood July Hip. Mansard ROOF: Midge Gambrel Flat Hip. Mansard Tower Cupola Dormer windows Balustrade Grillwork
FOUNDATION/BASEMENT: High Regular Low Material Track
4, DESCRIPTION
BIBLIOGRAPHY AND/OR REFERENCE 1870 Atlas - S. Jay 1898 "O'Brien Charles Tufts Jred Sauchioni Brock RESTRICTIONS RESTRICTIONS
Original Owner: HIS JOSEPH COMMISSION OF THE STATE OF THE

_ Page_

Deed Information: Book Number____